



The gap between coil IDM and flywheel IDM must be 0,35 mm in the central part (red indicator) and 0,50 mm in the lateral parts (green indicators).